

C.O.C.: DW105314

REPORT No. B21-36075

**Report To:**

**Property Management Inc**  
 323 Dundas Street East, Unit 3,  
 Trenton Ont K8V 5W5 Canada

**Attention:** Isaac Berman

**Caduceon Environmental Laboratories**

285 Dalton Ave  
 Kingston Ontario K7K 6Z1  
 Tel: 613-544-2001  
 Fax: 613-544-2770

DATE RECEIVED: 02-Nov-21

JOB/PROJECT NO.: HMR Estates Pump House

DATE REPORTED: 09-Nov-21

P.O. NUMBER:

SAMPLE MATRIX: Drinking Water

WATERWORKS NO. 260027768

<b>Client I.D.</b>	19A Buffalo Dr.	Pumphouse-Raw	Pumphouse	
<b>Sample I.D.</b>	B21-36075-1	B21-36075-2	B21-36075-3	
<b>Date Collected</b>	02-Nov-21	02-Nov-21	02-Nov-21	

Parameter	Units	R.L.	Reference Method	Date/Site Analyzed				
Total Coliform	cfu/100mL	1	MOE E3407	02-Nov-21/K	0	0		
E coli	cfu/100mL	1	MOE E3407	02-Nov-21/K	0	0		
Heterotrophic Plate Count	cfu/mL	10	SM9215D	02-Nov-21/K	< 10			
Nitrite (N)	mg/L	0.1	SM4110C	05-Nov-21/O			< 0.1	
Nitrate (N)	mg/L	0.1	SM4110C	05-Nov-21/O			< 0.1	



Michelle Dubien  
 Lab Manager

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \*

Site Analyzed=K-Kingston, W-Windsor, O-Ottawa, R-Richmond Hill, B-Barrie

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from