

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW118317

REPORT No. B21-37879

Report To:	Caduceon Environmental Laboratories
Property Management Inc	285 Dalton Ave
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001
Attention: Isaac Berman	Fax: 613-544-2770
DATE RECEIVED: 17-Nov-21	JOB/PROJECT NO.: HMR Estates Pump House
DATE REPORTED: 22-Nov-21	P.O. NUMBER:
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768

	Parameter Units R.L. Reference Method Date Analyzed/Site		Total Coliform	E coli	Heterotrophic Plate Count	
			cfu/100mL	cfu/100mL	cfu/mL	
			1	1	10	
			MOE E3407	MOE E3407	SM9215D	
			17-Nov-21/K	17-Nov-21/K	17-Nov-21/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr.	B21-37879-1	17-Nov-21	0	0	< 10	

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from