

ENVIRONMENTAL LABORATOR ES Client committed. Quality assured.

## CERTIFICATE OF ANALYSIS

**Final Report-Microbiology** 

## C.O.C.: DW116138

## REPORT No. B21-38230

Report To:	Caduceon Environmental Laboratories	
Property Management Inc	285 Dalton Ave	
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1	
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001	
Attention: Isaac Berman	Fax: 613-544-2770	
DATE RECEIVED: 22-Nov-21	JOB/PROJECT NO.: 104 Ellisville Rd - Pumphouse	
DATE REPORTED: 24-Nov-21	P.O. NUMBER:	
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260019591	

	Parameter		Total Coliform	E coli		
	Units	Units R.L. Reference Method		cfu/100mL		
	R.L.			1		
	Reference Meth			MOE E3407		
	Date Analyzed/S	Site	22-Nov-21/K	22-Nov-21/K		
Client I.D.	Sample I.D.	Date Collected				
#26	B21-38230-1	22-Nov-21	0	0		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an \* Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from