

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW116141 REPORT No. B21-39221

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 30-Nov-21 DATE REPORTED: 03-Dec-21

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter	Parameter Units R.L. Reference Method		E coli	Heterotrophic Plate Count	
	Units			cfu/100mL	cfu/mL	
	R.L.			1 MOE E3407	10 SM9215D	
	Reference Meth					
	Date Analyzed/Site		30-Nov-21/K	30-Nov-21/K	30-Nov-21/K	
Client I.D.	Sample I.D.	Date Collected		•		
19A Buffalo Dr	B21-39221-1	30-Nov-21	0	0	< 10	

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology