

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW116149

REPORT No. B21-40709

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 14-Dec-21	JOB/PROJECT NO.: HMR Estates Pump House			
DATE REPORTED: 16-Dec-21	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768			

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units	Units		cfu/100mL	cfu/mL	
	R.L.		1	1	10	
	Reference Method Date Analyzed/Site		MOE E3407 14-Dec-21/K	MOE E3407 14-Dec-21/K	SM9215D 14-Dec-21/K	
Client I.D.	Sample I.D.	Date Collected				·
19A Buffalo Dr	B21-40709-1	14-Dec-21	0	0	< 10	
Pumphouse-Raw	B21-40709-2	14-Dec-21	0	0		

E. Sumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from