

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW116157 REPORT No. B21-41891

Report To:

Property Management Inc

323 Dundas Street East, Unit 3, Trenton Ont K8V 5W5 Canada **Attention:** Isaac Berman

DATE RECEIVED: 29-Dec-21

DATE REPORTED: 04-Jan-22

SAMPLE MATRIX: Drinking Water

Caduceon Environmental Laboratories

285 Dalton Ave

Kingston Ontario K7K 6Z1

Tel: 613-544-2001 Fax: 613-544-2770

JOB/PROJECT NO.: HMR Estates Pump House

P.O. NUMBER:

WATERWORKS NO. 260027768

	Parameter Units R.L. Reference Method Date Analyzed/Site		Total Coliform	E coli	Heterotrophic Plate Count		
			cfu/100mL	cfu/100mL	cfu/mL		
			1	1	10		
			MOE E3407	MOE E3407	SM9215D		
			29-Dec-21/K	29-Dec-21/K	29-Dec-21/K		
Client I.D.	Sample I.D.	Date Collected				·	
19A Buffalo Dr	B21-41891-1	29-Dec-21	0	0	< 10		

E. Lumore

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Evan Livermore Supervisor/Microbiology