

Client committed. Quality assured.

CERTIFICATE OF ANALYSIS

Final Report-Microbiology

C.O.C.: DW116443

REPORT No. B22-03806

Report To:	Caduceon Environmental Laboratories			
Property Management Inc	285 Dalton Ave			
323 Dundas Street East, Unit 3,	Kingston Ontario K7K 6Z1			
Trenton Ont K8V 5W5 Canada	Tel: 613-544-2001			
Attention: Isaac Berman	Fax: 613-544-2770			
DATE RECEIVED: 08-Feb-22	JOB/PROJECT NO.: HMR Estates Pump House			
DATE REPORTED: 11-Feb-22	P.O. NUMBER:			
SAMPLE MATRIX: Drinking Water	WATERWORKS NO. 260027768			

	Parameter		Total Coliform	E coli	Heterotrophic Plate Count	
	Units		cfu/100mL	cfu/100mL	cfu/mL	
	R.L.		1	1	10	
	Reference Meth	od	MOE E3407	MOE E3407	SM9215D	
	Date Analyzed/S	Site	09-Feb-22/K	09-Feb-22/K	09-Feb-22/K	
Client I.D.	Sample I.D.	Date Collected				
19A Buffalo Dr	B22-03806-1	08-Feb-22	0	0	< 10	
Pumphouse-Raw	B22-03806-2	08-Feb-22	0	0		

R. Jeco Bo

R.L. = Reporting Limit

Test methods may be modified from specified reference method unless indicated by an * Site Analyzed=K-Kingston,W-Windsor,O-Ottawa,R-Richmond Hill,B-Barrie

Richard Lecompte Laboratory Supervisor

The analytical results reported herein refer to the samples as received. Reproduction of this analytical report in full or in part is prohibited without prior consent from